

BUILDING SAFETY CERTIFICATE

No. 4847

Dated: 22/07/2025

It is certified that the existing building St. Joseph's English High School, at Gut No.86 Part, Beside Bhadola Road Sundarkhed, Tq. Dist Buldhana is having block (s) / floor(s) as per details below:

Detail of Block(S) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of floor (S) Block	1 G+3	-	-	-	-	-

The building is owned/occupied by Society-Congregation of the Sisters of our Lady of Dolours, Buldhana Reg.no.F-1866.(St. Joseph's English High School, Bhadola Road Sundarkhed, Tq. Dist Buldhana) have complied with the Building safety requirements in accordance with National Building code rule, concerned of Public works Subdivision Buldhana and verified as per structural Audit Report Submitted by Mr. Mandar M. Joshi, Private Structural Engineer, Buldhana on 29.06.2025 in the presence of Sr. Sagunthala-secretary, St. Joseph's English High School Bhadola Road Sundarkhed, Buldhana & that building / premises is fit (Subjected to rectify the observations pointed out by structural Engineer) for occupancy for running school with effect from 01.07.2025 for a period of 1 year in accordance with rule and subject to compliance of the specific conditions as appended.

1. Column & steel exposed :- No
2. Foundation settlement :- No
3. Major cracks in column/beams :- No
4. Seepage / Leakages :- No

Issued on 01.07.2025 At Buldhana by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Sub Divisional Engineer
P.W.Sub-Division, Buldhana

Signature with Seal :

Name :

Designation :

Name & Address of

Department/Office:

Executive Engineer
Public Works Division
Buldhana

THE SECRETARY
CONGREGATION OF THE SISTERS
OF OUR LADY OF DOLOURS
BULDANA

Principal
St. Joseph's English High School
Buldhana.
CBSE Affiliation No.1130602